

Location Name: BIG TIMER 32-19, API #: 071-08761, Insp. #:695103932



Colorado Oil & Gas Conservation Commission

27-26-401-104-70265-2101-9m-150°



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Phone 1: LOCATION

**EVERGREEN**  
**NATURAL RESOURCES LLC**  
**BIG TIMER 32-19**  
**T32S, R65W, SEC. 19: SWNE**  
**CR 51**  
**LAT. 37.24599 / LONG. -104.71204**  
**API# 05-071-08761**  
**Emergency Number: 911**  
**or (719)846-7898**  
**WDID 1910419 / PERMIT #72353-F1**

Colorado Oil & Gas Conservation Commission  
37.24621, -104.71254, 2158.0m, 12°



Colorado Oil & Gas Conservation Commission

37.24604, -104.71267, 2163.0m, 58°

2021/02/01 14:34:18



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Phone 3: PILE OF E&P WASTE APPEARS TO BE FRAC SAND AND PERF DUST BAILED FROM WELL BORE NEXT TO WELLHEAD. COMPLY WITH RULE 905. AND 1002.F.(2)F**



Colorado Oil & Gas Conservation Commission  
37.24602, -104.71259, 2160.0m, 259°  
2021/02/01 14:34:43



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Phone 4: E&P WASTE APPEARS TO BE PERF DUST FLOATING IN STANDING WATER NEXT TO WELLHEAD. COMPLY WITH RULE 905 AND 1002.F.(2)F**



Colorado Oil & Gas Conservation Commission  
37.24601, -104.71259, 2159.0m, 104°  
2021/02/01 14:35:02



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Phone 5: E&P WASTE APPEARS TO BE PERF DUST ON SNOW AND GRASS BY WELLHEAD NEST TO PIT.  
COMPLY WITH RULE 905 AND 1002.F.(2)F**



Colorado Oil & Gas Conservation Commission

37.24601, -104.71259, 2159.0m, 38°

2021/02/01 14:35:58



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Phone 6: ANOTHER IMAGE OF E&P WASTE APPEARS TO BE PERF DUST ON SNOW AND GRASS BY WELLHEAD NEST TO PIT. COMPLY WITH RULE 905 AND 1002.F.(2)F**



Colorado Oil & Gas Conservation Commission

37.24598, -104.71258, 2154.0m, 270°

2021/02/01 14:37:47



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Phone 7: CLOSER IMAGE OF E&P WASTE APPEARS TO BE PERF DUST ON SNOW AND GRASS BY WELLHEAD NEST TO PIT. COMPLY WITH RULE 905 AND 1002.F.(2)F**



Colorado Oil & Gas Conservation Commission

37.24598, -104.71258, 2154.0m, 30°

2021/02/01 14:37:58



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Phone 8: TRASH NEAR WELLHEAD. COMPLY WITH RULE 606.**



Colorado Oil & Gas Conservation Commission

37.24598, -104.71258, 2154.0m, 178°

2021/02/01 14:38:17



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Phone 9: UNUSED EQUIPMENT STORED ON LOCATION (OLD PUMP AND SUCKER RODS). **COMPLY WITH RULE 606.**



Colorado Oil & Gas Conservation Commission

37.24598, -104.71257, 2154.0m, 308°

2021/02/01 14:37:01



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Phone 10: OIL IN COMPRESSOR ENGINE SKID. COMPLY WITH RULE 1002.f.(2)A AND Comply with general provisions of the oil and gas act for wildlife protection.**



Colorado Oil & Gas Conservation Commission

37.24598, -104.71257, 2153.0m, 207°

2021/02/01 14:37:15



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Phone 11: DRAIN PAN WITH OIL IN COMPRESSOR ENGINE SKID. COMPLY WITH RULE 1002.f.(2)A AND Comply with general provisions of the oil and gas act for wildlife protection.**



Colorado Oil & Gas Conservation Commission

37.24601, -104.71259, 2159.0m, 133°

2021/02/01 14:36:12



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Phone 12: AREA OF IMPACTED SOIL NEAR MUFFLER OUTLET FROM COMPRESSOR ENGINE.**



Colorado Oil & Gas Conservation Commission

37.24603, -104.71266, 2159.0m, 46°

2021/02/08 14:35:44



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Phone 13: PHOTO TAKEN 7 DAYS AFTER ORIGINAL INSPECTION SHOWING THAT NOTHING HAS BEEN CLEANED UP. NOT I HAVE NOT TURNED ORIGINAL INSPECTION INTO THE OPERATOR PRIOR TO THIS PHOTO BEING TAKEN DUE TO WAITING FOR COMPLAINT.**



Colorado Oil & Gas Conservation Commission

37.24603, -104.71266, 2158.0m, 72°

2021/02/08 14:35:56



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Phone 14: PHOTO TAKEN 7 DAYS AFTER ORIGINAL INSPECTION SHOWING THAT NOTHING HAS BEEN CLEANED UP. NOTE: I HAVE NOT TURNED ORIGINAL INSPECTION INTO THE OPERATOR PRIOR TO THIS PHOTO BEING TAKEN DUE TO WAITING FOR COMPLAINT.**



Colorado Oil & Gas Conservation Commission

37.24603, -104.71266, 2158.0m, 98°

2021/02/08 14:36:12



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Phone 15: PHOTO TAKEN 7 DAYS AFTER ORIGINAL INSPECTION SHOWING THAT NOTHING HAS BEEN CLEANED UP. NOTE: I HAVE NOT TURNED ORIGINAL INSPECTION INTO THE OPERATOR PRIOR TO THIS PHOTO BEING TAKEN DUE TO WAITING FOR COMPLAINT.**



Colorado Oil & Gas Conservation Commission

37.24684, -104.70879, 2174.0m, 198°

2021/02/08 14:33:31



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Phone 16: DRIP JUST EAST OF BIG TIMER LOCATION NEAR REILLY CREEK. AT TIME OF INSPECTION I DO NOT SEE ANY EVEDANCE THAT THE DRIP HAS BEEN DRAINED ON THE GROUND.**