

Inspection Photos

Loc#335351

Operator: Caerus

Insp#: 692403146

Insp Date: 3/4/21





Photo#1:
Overviews of Location.

March 4, 2021



Photo#2:
Interim area.



Photo#3:
Portion of entry needing maintenance.

March 4, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus GMR Loc#335351



Photo#4:
Possible Tank leak.

March 4, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus GMR Loc#335351