

Final Reclamation Inspection

March 26, 2021

Operator: BAYSWATER EXPLORATION AND PRODUCTION LLC - #10261

Location ID: 310231

Inspection Document #: 697502711

Weld County, CO

NENE Section 26 T7N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: LIND FARMS #26-11
Location ID: 310231



Photo 1. Photo taken from the southern location, facing North. Photo illustrates Operator has removed all unused equipment and performed final reclamation activities per Rule 1004 standards.
Note: oil and gas equipment in the background is from a separate location not associated with this PA location.

Inspection Photos
Location Name: LIND FARMS #26-11
Location ID: 310231



Photo 2. Photo taken from the southern location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: LIND FARMS #26-11
Location ID: 310231



Photo 3. Photo taken from the southern location, facing Northeast. See comments under Photo 1.