



39.91866, -108.22926, 7002.9ft, 39°
04/09/2021 03:07:45 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

Piceance Creek Unit 197-36A API: 05-103-1118X
Inspection: 701500286



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Processing equipment.

Piceance Creek Unit 197-36A API: 05-103-1118X
Inspection: 701500286





COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Separator & communication building.

Piceance Creek Unit 197-36A API: 05-103-1118X
Inspection: 701500286



39.91843, -108.22913, 7012.6ft, 40°
04/09/2021 03:10:06 PM



39.91854, -108.22934, 7017.2ft, 29°
04/09/2021 03:10:37 PM



39.91955, -108.22759, 7035.1ft, 217°
 04/09/2021 03:04:33 PM