



39.91167, -108.19866, 7229.9ft, 357°
04/09/2021 04:05:25 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

API: 05-103-11239 to 11248
Piceance Creek Unit 296-5A Inspection: 701500290





39.91268, -108.19817, 7238.2ft, 33°
04/09/2021 04:10:14 PM



39.91266, -108.1985, 7234.9ft, 37°
04/09/2021 04:09:46 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 5. Ruts on location.

API: 05-103-11239 to 11248
Piceance Creek Unit 296-5A Inspection: 701500290



39.91184, -108.19878, 7229.1ft, 347°
04/09/2021 04:05:46 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 6. Ruts on location.

API: 05-103-11239 to 11248
Piceance Creek Unit 296-5A Inspection: 701500290

