

Inspection Photos
Location Name: Buchner 1-2H
Location ID: 427041



Photo 1 – Pumping Unit



Photo 2 – Wellhead Sign – Number NOT Current

Inspection Photos
Location Name: Buchner 1-2H
Location ID: 427041



Photo 3 – Stained Soil at Gas Engine



Photo 4 – Stained Soil at Gas Engine

Inspection Photos
Location Name: Buchner 1-2H
Location ID: 427041



Photo 5 – Stained Soil at Gas Engine



Photo 6 – Stained Soil at Gas Engine



Inspection Photos
Location Name: Buchner 1-2H
Location ID: 427041



Photo 7 – Wildlife Netting installed and Debris/Trash removed



Photo 8 – Wellhead

Inspection Photos
Location Name: Buchner 1-2H
Location ID: 427041



Photo 9 – Stained Soil at Gas Engine Exhaust has been cleaned up



Photo 10 – Stained Soil cleaned up

Inspection Photos
Location Name: Buchner 1-2H
Location ID: 427041



Photo 11 – Loadline – Cover has been replaced and Soil cleaned up



Photo 12 – Loadline – Cover has been replaced and Soil cleaned up

Inspection Photos
Location Name: Buchner 1-2H
Location ID: 427041



Photo 13 – Heater Treater



Photo 14 – Heater Treater Soil cleaned up

Inspection Photos
Location Name: Buchner 1-2H
Location ID: 427041



Photo 15 – Tank Battery



**Photo 16 – Middle Crude Oil Tank – Content and Capacity
Label fading**

Inspection Photos
Location Name: Buchner 1-2H
Location ID: 427041



Photo 17 – ECD



Photo 18 – Flare – Fresh Oil still running down

Inspection Photos
Location Name: Buchner 1-2H
Location ID: 427041



Photo 19 – Flare – Fresh Oil still running down



Photo 20 – Flare – Fresh Oil still running down