

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KNIGHT-67S95W /5SENE

Location ID: 334652



Photo #3518 from entrance to location.



Photo #3519 from entrance to location.



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KNIGHT-67S95W /5SENE

Location ID: 334652



Photo #3520 Location lacks stabilization



Photo #2721 from inspection #699802481 conducted on 1/26/21.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KNIGHT-67S95W /5SENE

Location ID: 334652



Photo #3523 Location lacks stabilization



Photo #2722 from inspection #699802481 conducted on 1/26/21.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KNIGHT-67S95W /5SENE

Location ID: 334652



Photo #3522 no form of tracking control at entrance to location.