

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

04/19/2021

Submitted Date:

04/20/2021

Document Number:

699103402

**FIELD INSPECTION FORM**
 Loc ID 431774 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
,		EHSRC@bonanzacrk.com	All Inspections
Kraich, Adam		adam.kraich@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
431774	LOCATION	AC			-	Wetco Farms A-4 Pad	AC

**General Comment:**

**Inspected Facilities**

Facility ID: 431774 Type: LOCATION API Number: - Status: AC Insp. Status: AC

**Producing Well**Comment: AC

Corrective Action:

Date:

**Complaint**

Comment:

Inspection in response to complaint.  
 Field Inspector Assigned: Adam Burns  
 Complaint Received  
 Date: 3-24-2021  
 Complaint Contacted: Curt Meyer  
 Location ID # 431774  
 Inspection Document # 699100998  
 18. Complaint Document # 200449590  
 Nature of Complaint: Low Frequency Noise  
 Field Inspector Actions:  
 On 3-24-2021, I Adam Burns area field inspector was assigned a complaint (low frequency, vibration) received by COGCC staff in reference to Noise. The complainant filed a complaint with the commission on the COGCC website.  
 On 4-9-2021, I along with supervisor Adam Kraich set a sound meter at 31736 County Road 50, Kersey, CO 80644. 40.3472, -104.4566. The sound audit began 4-9-2020 and ended 4-16-2020. Only nighttime (19:00 to 07:00) hours were used in the study. Additionally, the only usable data in the study was highlighted in green on the weather data sheet.  
 The proximity and consistent operation of the Wetco Farm tank battery, place it as the possible sound source of the non compliant low frequency levels.  
 The resulting data from the study, is an LEQ 2 of 64.6 DB, which suggest noncompliance of Rule 423-1.  
 See report for corrective action detail.  
 See attachments for sound audit, and weather detail.  
 All information reviewed and site inspection information were submitted to the COGCC for further review.  
 END OF REPORT

Corrective Action: Comply with Rule 423-1

Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402664754	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5408340">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5408340</a>
699103409	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5408334">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5408334</a>
699103410	Sound Audit	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5408335">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5408335</a>
699103412	Weather Data	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5408336">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5408336</a>