

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/13/2021

Submitted Date:

04/25/2021

Document Number:

688310379

FIELD INSPECTION FORM

 Loc ID 435195 Inspector Name: Sherman, Susan On-Site Inspection 2A Doc Num: _____
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

1 Number of Corrective Actions

-
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Operator Information:

OGCC Operator Number: 10706

Name of Operator: D90 ENERGY LLC

Address: 202 TRAVIS STREET #402

City: HOUSTON State: TX Zip: 77002

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|--------------|---------------------|------------------|
| James, Cole | 719-892-0378 | cj0378@hotmail.com | Pumper |
| Craig, Bill | 719-650-4991 | jwcranch@gmail.com | |
| Oakes, Kevin | 713-227-0391 | kevin@d90energy.com | Designated Agent |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 435194 | WELL | TA | 10/01/2020 | OW | 073-06563 | JOHN CRAIG 2-2 | TA |

General Comment:

Reinspection

Document #402190896 Form 10 (CO)(CC) Type: Change of Operator IN PROCESS 3/25/2020

Document #402492184 WARN -00 Letter IN PROCESS 9/17/2020, Form 7s delinquent, Form 4 TA status request not current

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|-------------------------------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | Still D90, Form 10 still in process | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|----------------------|-------|--|
| Comment: | <input type="text"/> | Date: | |
| Corrective Action: | <input type="text"/> | | |

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

| | | | |
|--------------------|-----------|-------|--|
| Type | PUMP JACK | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | LOCATION | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Equipment:

| Type | Quantity | Comment | corrective date |
|--------------------|------------|---------|-----------------|
| Deadman # & Marked | # 4 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Bradenhead | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Prime Mover | # 1 | | |
| Comment: | gas engine | | |
| Corrective Action: | | Date: | |
| Pump Jack | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|---------------------|---------|--------|
| | | | CENTRALIZED BATTERY | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | | | | |
|------------------|--|--|--|--|--|
| Condition | | | | | |
| Other (Content) | | | | | |
| Other (Capacity) | | | | | |
| Other (Type) | | | | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Venting:

| | | | | |
|--------------------|----|--|--|-------|
| Yes/No | NO | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Flaring:

| | | | | |
|--------------------|--|--|--|-------|
| Type | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Inspected Facilities

Facility ID: 435194 Type: WELL API Number: 073-06563 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI/TA
10/2020 last production data submitted. No Form 4 for SI/TA status approval was submitted.

Corrective Action: See Warning Letter #402492184. Date: 12/31/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------------------|---|
| 688310416 | D90 Energy John Craig 2-2 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5413542 |