

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402667846

Date Received:  
04/22/2021

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 100264

Name of Operator: XTO ENERGY INC

Address: 110 W 7TH STREET

City: FORT WORTH State: TX Zip: 76102

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Jessica Dooling

Phone

970-769-0648

Email

jessica.dooling@exxonmobil.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 701500284

Inspection Date: 04/09/2021

FIR Submit Date: 04/12/2021

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: XTO ENERGY INC

Company Number: 100264

Address: 110 W 7TH STREET

City: FORT WORTH State: TX Zip: 76102

### LOCATION - Location ID: 413466

Location Name: Piceance Creek Unit Number: 296-6B County: RIO BLANCO

Qtrqr: NWSE Sec: 6 Twp: 2S Range: 96W Meridian: 6

Latitude: 39.905270 Longitude: -108.205189

### FACILITY - API Number: 05-103- -00 Facility ID: 412626

Facility Name: Piceance Creek Unit Number: 296-6B5

Qtrqr: NWSE Sec: 6 Twp: 2S Range: 96W Meridian: 6

Latitude: 39.905270 Longitude: -108.205189

### CORRECTIVE ACTIONS:

1 ☒ CA# 148293

Corrective Action: Install sign to comply with Rule 605.d.

Date: 06/12/2021

Response: CA COMPLETED

Date of Completion: 04/16/2021

Operator  
Comment:

Sign installed on wellhead 4/16/2021, please see attached photo

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

2 ☒ CA# 148294

Corrective Action: Install, maintain, or provide documentation of post construction management plan or BMP's.

Date: 06/12/2021

Response: CA COMPLETED

Date of Completion: 04/21/2021

Operator  
Comment:

Rutting on well pad resolved and cattle guard cleaned out 4/21/2021, please see attached photos

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective actions completed, please see attached photos

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jessica Dooling

Signed: \_\_\_\_\_

Title: Lead Regulatory Coordinat

Date: 4/22/2021 12:13:15 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402667846	FIR RESOLUTION SUBMITTED
402667848	20210416 Wellhead Sign
402667851	20210421 Resolved Rutting on pad
402667852	20210421 Cattle guard

Total Attach: 4 Files