

Inspection Photos

Location Name: LARAMIE ENERGY LLC BCU /12E Pad

Location ID: 334488



Photo #3733 from entrance to location.



Photo #3734 from entrance to location.

Inspection Photos

Location Name: LARAMIE ENERGY LLC BCU /12E Pad

Location ID: 334488



Network time is not synchronize
Local: May 6, 2021 at 1:09:06 PM MD



Network time is not synchronize
Local: May 6, 2021 at 1:09:21 PM MD

Photo #3735 Location lacks stabilization.

Photo #3736 Location lacks stabilization.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: LARAMIE ENERGY LLC BCU /12E Pad

Location ID: 334488



Photo #3737 No form of tracking BMP located at entrance to location.