

**Inspection Photos**  
**Location Name: State 26-2**  
**Location ID: 327091**



**Photo 1 – Pumping Unit**



**Photo 2 – Tank Battery, Deadman Anchors now Marked**

**Inspection Photos**  
**Location Name: State 26-2**  
**Location ID: 327091**



**Photo 3 – Wellhead**



**Photo 4 – Tank Battery Sign. Produced Water Label  
Weathered**



**Inspection Photos**  
**Location Name: State 26-2**  
**Location ID: 327091**



**Photo 5 – Separator**



**Photo 6 – Unmarked Riser at Separator**

Inspection Photos  
Location Name: State 26-2  
Location ID: 327091



Photo 7 – Gas Meter




Photo 8 – Gas Meter Calibration Card NOT Up to Date