

TEP  
Burkle A  
Location # 335540



location



location

TEP  
Burkle A  
Location # 335540



location



Lack of stabilization/compaction/drain

TEP  
Burkle A  
Location # 335540



Drain on edge of location



Outlet of drain

TEP  
Burkle A  
Location # 335540



**Sediment migration from drain on edge of location**



TEP  
Burkle A  
Location # 335540



cut slope not stabilized



cut slope not stabilized

TEP  
Burkle A  
Location # 335540



**Riling/ cut slope not stabilized**

