

# Inspection Photos

6/15/2021

Operator: SG INTERESTS I LTD - 77330

Location ID: 428197

Gunnison County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 428197



**Photo 1:** Photo taken from the southwest end of the Location, facing north. Photos 1-3 provide an overview of the Location from north, northeast to east.

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 428197



**Photo 2:** See comments under photo 1.



Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 428197



**Photo 3:** See comments under photo 1.

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 428197



**Photo 4:** Photo taken from the cut-slopes on the northeast corner of the Location, facing west. Photo shows control measures (short term and long term) control measures to protect and stabilize the cut-slopes remain missing or insufficient.



Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 428197



**Photo 5:** Photo taken from the cut-slopes on the northeast corner of the Location, facing northeast. Photo shows control measures (short term and long term) control measures to protect and stabilize the cut-slopes remain missing or insufficient.



Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 428197



**Photo 6:** Photo taken from the cut-slopes on the southeast corner of the Location, facing north. Photo shows control measures (short term and long term) control measures to protect and stabilize the cut-slopes remain missing or insufficient.



Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 428197



**Photo 7:** Photo off wellhead and cellar. Photo shows control measures to prevent wildlife access to the cellar, and to protect wildlife resources remain missing or inadequate. Photo also shows fluids/chemicals within cellar have not been removed.



Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 428197



**Photo 8:** Continued from photo 7. Photo shows wildlife mortality (ground squirrel) within the cellar. Control measures to prevent wildlife access to the cellar, and to protect wildlife resources remain missing or inadequate. Photo also shows fluids/chemicals within cellar have not been removed.

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 428197



**Photo 10:** Continued from photo 7. Photo shows wildlife mortality (ground squirrel) within the cellar. Control measures to prevent wildlife access to the cellar, and to protect wildlife resources remain missing or inadequate. Photo also shows fluids/chemicals within cellar have not been removed.

