

Inspection Photos
Location Name: Deal Gulch
Location ID: 428535



Photo 1. Overview of location taken at entrance facing southeast.



Photo 2. No bradenhead access apparent.



Inspection Photos
Location Name: Deal Gulch
Location ID: 428535



Photo 3. No bradenhead access apparent.



Photo 4. No bradenhead access apparent.



Inspection Photos
Location Name: Deal Gulch
Location ID: 428535




Photo 5. No bradenhead access apparent. Stained soil on location.



Photo 6. Stained soil on location.

