

Inspection Photos

API#107-06206

Operator: North Finn

Insp#: 692403587

Insp Date: 6/24/2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Anchors, Debris, lines, risers have been removed.

Photo#2:
Anchors, Debris, lines, risers have been removed.

June 24, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: North Finn PA Breeze API#107-06206