

Inspection Photos
Location Name:
Wilmoth C/ 14-29 Tank Battery
Facility ID: 447335



Photo #1 Tank Battery




Photo #2 Production Equipment

Inspection Photos
Location Name:
Wilmoth C/ 14-29 Tank Battery
Facility ID: 447335



Photo #3 Missing Bird protector



Photo #4 Missing Bird protector