

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/28/2021

Submitted Date:

06/28/2021

Document Number:

699103938

FIELD INSPECTION FORM

Loc ID 425056 Inspector Name: Burns, Adam On-Site Inspection 2A Doc Num: _____

Operator Information:
OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
6 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
447335	TANK BATTERY	AC	08/19/2016		-	WILMOTH C 14-29 TANK	AC

General Comment:

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#		corrective date
Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Bird Protectors	# 3		
Comment:	The south separator is missing the bird protector. See attached photos.		
Corrective Action:	Install or repair wildlife protection equipment.		Date: 07/05/2021

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	BV CONCRETE		,
Comment:	Shares containment with crude oil tanks.				
Corrective Action:				Date:	

Paint

Condition	<input type="text"/>
Other (Content)	<input type="text"/>

Other (Capacity) 60 BBL	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	300 BBLs	STEEL AST		40.319500,-104.520100	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 447335 Type: TANK API Number: - Status: AC Insp. Status: AC**Producing Well**Comment: AC

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Monday 6/28/21 at approximately 0732hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Wilmoth C/14-29 Tank Battery of Noble Energy, at Facility ID # 447335 in Weld County, Colorado. During this inspection the following possible compliance issues were observed: The south separator is missing the bird protector. Install or repair wildlife protection equipment. With a corrective action date of 7/5/21 See attached photos. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	burnsa	06/28/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402731173	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5465382
699103939	Inspection Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5465369