

Inspection Photos

7/07/2021

Operator: BLACK HILLS / LARAMIE

Location ID: 312436

Mesa County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: BLACK HILLS / LARAMIE
Location ID: 312436



Photo 1: Photo taken from the north end of the Location, facing southeast. Photo 1-2 provide an overview of the Location from southeast to south. Photos show final reclamation has not been completed on the Location in accordance with 1004 rules.

Inspection Photos
Operator Name: BLACK HILLS / LARAMIE
Location ID: 312436



July 7, 2021
39.18377539N 108.07700926W

Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: BLACK HILLS / LARAMIE
Location ID: 312436



Photo 3: Photo taken from the southeast end of the Location, facing northeast. Photo shows cut slopes and edge of the pad.

Inspection Photos
Operator Name: BLACK HILLS / LARAMIE
Location ID: 312436



July 7, 2021
39.18334002N 108.07655249W

Photo 4: Photo taken from the cut slopes on the southeast end of the Location. Photo shows erosion degradation observed on the slopes.

Inspection Photos
Operator Name: BLACK HILLS / LARAMIE
Location ID: 312436



Photo 5: Photo taken from the cut slopes on the southeast end of the Location. Photo shows erosion degradation observed on the slopes.

Inspection Photos
Operator Name: BLACK HILLS / LARAMIE
Location ID: 312436



Photo 6: Photo taken from the cut slopes on the southeast end of the Location. Photo shows erosion degradation observed on the slopes.

Inspection Photos
Operator Name: BLACK HILLS / LARAMIE
Location ID: 312436



Photo 7: Photo taken from the west end of the Location, facing north. Photo shows fill slopes of the Location.

Inspection Photos
Operator Name: BLACK HILLS / LARAMIE
Location ID: 312436



Photo 8: Photo taken from the west end of the Location, facing southwest. Photo shows fill slopes of the Location.

Inspection Photos
Operator Name: BLACK HILLS / LARAMIE
Location ID: 312436



Photo 10: Photo shows example of noxious weeds observed on the Location.

Inspection Photos
Operator Name: BLACK HILLS / LARAMIE
Location ID: 312436



Photo 11: Photo shows example of noxious weeds observed on the Location.

Inspection Photos
Operator Name: BLACK HILLS / LARAMIE
Location ID: 312436



Photo 12: Photo taken from the south end of the Location, facing south. Photo shows access road has not been reclaimed.