

Inspection Photos
Location Name: Jillson A 1
API 05-123-08777 Spill ID: 478617



Photo 1 Well Sign



**Photo 2 Excavation at well, water in bottom of excavation,
weeping well casing**



Inspection Photos
Location Name: Jillson A 1
API 05-123-08777 Spill ID: 478617



Photo 3 Excavation at well



Photo 4 Tank Battery Sign

Inspection Photos
Location Name: Jillson A 1
API 05-123-08777 Spill ID: 478617



Photo 5 Leaky header



Photo 6 Open top partially buried produced water vessel