


## Inspection Photos

Location Name: KEHN USX AA-66N63W /1NWNE

Location #: 310872



**Photo #1**

**Kehn USX AA 01-02 (05-123-27164) Wellsite**

**Plugged & Abandoned | PA**

**~ 10 yds.**



**Photo #2**

**Kehn USX AA 01-02 Wellsite**

**Plugged & Abandoned | PA**

**Corrective Action: Unnecessary Equipment  
Well tubing**

## Inspection Photos

Location Name: KEHN USX AA-66N63W /1NWNE

Location #: 310872



Colorado Oil & Gas Conservation Commission  
Weld County  
+40.519719, -104.379070  
261° W  
08-Jul-2021 16:51

### Photo #3

**Kehn USX AA 01-08** Battery site

**Inactive | Shut-down**

**Equipment documented Loc. ID 302162**

*Formerly served:*

*Kehn USX AA 01-02*

*Plugged & Abandoned | PA*



Colorado Oil & Gas Conservation Commission  
Weld County  
+40.519719, -104.379070  
320° NW  
08-Jul-2021 16:52

### Photo #4

**Kehn USX AA 01-08** Battery site

**Inactive | Shut-down**

**Battery sign**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources