

Inspection Photos
Operator: Simcoe
API: 067-08364
Date: 7/9/2021




Photo 1. View the project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Revegetation is progressing with crested wheatgrass, smooth brome, and sand dropseed.



Photo 3. View the northern project area from the northeastern corner facing westward.



Photos 4/5. View of debris within the project area that needs to be removed.



Photo 6. View the northern project area from the northeastern corner facing westward.