

Inspection Photos

Location Name: CAERUS PICEANCE LLC PUCKETT-67S97W /1SWNE

Location ID: 324312



Photo #4387 from entrance to location.



Photo #4388 Heating insulation open ended and not capped.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources