

Inspection Photos

Location Name: LARSON - USX AA-66N63W /19SENW

Location #: 306341



Photo #1

Larson - USX AA 19-6 (05-123-24479) Wellsite
Temporarily Abandoned | TA



Photo #2

Larson - USX AA 19-6 Battery site
Inactive | Shut-down
Formerly served:
Larson USX AA 19-3
Plugged & Abandoned | PA

Inspection Photos

Location Name: LARSON - USX AA-66N63W /19SENW

Location #: 306341



Photo #3

Larson - USX AA 19-6 Battery site

Inactive | Shut-down

Battery sign



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources