

Inspection Photos

Location Name: LARSON USX AA-66N63W /19NENW

Location #: 306342



Photo #1

Larson USX AA 19-3 (05-123-24480) Wellsite

Plugged & Abandoned | PA

~ 275 yds.



Photo #2

Larson - USX AA 19-6 Battery site

Inactive | Shut-down

Formerly served:

Larson USX AA 19-3

Plugged & Abandoned | PA

Inspection Photos

Location Name: LARSON USX AA-66N63W /19NENW

Location #: 306342



Photo #3

Larson - USX AA 19-6 Battery site

Inactive | Shut-down

Battery sign



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources