

Inspection Photos
Location Name: Van Schiack 5
Location ID: 313128



**Photo 1. Overview of location taken facing southwest.
Annual weeds on location.**



Inspection Photos
Location Name: Van Schaick 5
Location ID: 313128



Photo 2. Sediment migrating onto location.



Photo 3. Sediment migrating onto location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources