

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MOBIL-66S95W /26SWSW,

Location ID: 311558



Photo #4634 from entrance to location.



Photo #4635 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MOBIL-66S95W /26SWSW,

Location ID: 311558



Photo #4639 Unmarked deadman.



Photo #4336 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MOBIL-66S95W /26SWSW,

Location ID: 311558



Photo #4638 Location lacks stabilization.



Photo #4638 No form of tracking BMP located at entrance to location.