

Inspection Photos

API: 071-08113

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/16/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08113 | Date: 8/16/2021

Inspection Photos



Photo 1. Facing northeast along the main road near the electric gate. Stormwater is directed down the road side in this area which is contributing to erosion of the county road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08113 | Date: 8/16/2021

Inspection Photos



Photo 2. This culvert along the main road is partially washed out and needs to be repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08113 | Date: 8/16/2021

Inspection Photos



Photo 3. The same culvert inlet is filled in with sediment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08113 | Date: 8/16/2021

Inspection Photos



Photo 4. There is erosion along the side of the road which has exposed a pipe line shown at red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08113 | Date: 8/16/2021

Inspection Photos



Photo 5. Facing northwest toward the access road. This area is stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08113 | Date: 8/16/2021

Inspection Photos



Photo 6. Further west along the access road there is erosion along the road. BMP's need to be installed along the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08113 | Date: 8/16/2021

Inspection Photos



Photo 7. Facing back east along the access road. There is insufficient BMP's along this portion of the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08113 | Date: 8/16/2021

Inspection Photos



Photo 8. Facing northwest toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08113 | Date: 8/16/2021

Inspection Photos



Photo 9. Facing toward the well and pit. Water level is near 2 ft. freeboard and needs to be lowered.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08113 | Date: 8/16/2021