

Caerus Piceance LLC
Piceance unit 197-36A1
Location # 335962



location



location

Caerus Piceance LLC
Piceance unit 197-36A1
Location # 335962



location



location

Caerus Piceance LLC
Piceance unit 197-36A1
Location # 335962



location



Debris

Caerus Piceance LLC
Piceance unit 197-36A1
Location # 335962



Lack of labeling/failing containment



Lack of labeling/failing containment



Caerus Piceance LLC
Piceance unit 197-36A1
Location # 335962



Lack of labeling/failing containment



Lack of labeling/failing containment

Caerus Piceance LLC
Piceance unit 197-36A1
Location # 335962



Lack of stabilization/erosion



Lack of stabilization/erosion