

Final Reclamation Inspection

October 8, 2021

Operator: TINDALL OPERATING COMPANY - #88380

Location ID: 319436

Inspection Document #: 697503338

Weld County, CO

NWNE Section 7 T7N R58W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: DOROTHY #1
Location ID: 319436



Photo 1. Drone aerial imagery taken of the location. Photo illustrates the Operator has not performed final reclamation, including backfilling a pit.

Inspection Photos
Location Name: DOROTHY #1
Location ID: 319436



Photo 2. Drone aerial imagery taken of the location and access road, facing East. See comments under Photo 1.

Inspection Photos
Location Name: DOROTHY #1
Location ID: 319436



Photo 3. Photo taken from the open pit. Photo illustrates the pit remains open.



Inspection Photos
Location Name: DOROTHY #1
Location ID: 319436



Photo 4. Photo taken from the location, facing Northeast. Photo illustrates equipment being stored at location.