

**Inspection Photos**  
**Location Name: David Howard #6**  
**Location ID: 318676**



**Photo 1 Debris Road access into location**



**Photo 2 loc pic**

**Inspection Photos**  
**Location Name: David Howard #6**  
**Location ID: 318676**



**Photo 3 Well head**



**Photo 4 Debris : dead weeds on location.**