

Inspection Photos  
Operator: Simcoe  
API: 067-06659  
Date: 10/13/2021



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Revegetation is progressing with irrigated grasses such as smooth brome, red fescue, and thickspike whatgrass.

# Kochia debris



Photo 3. View of dense kochia debris within the project area and growing around partially buried vessel.



Photo 4. View of Canada thistles (approx. 100 individuals) within the northwestern project area.



Photo 5. View of reference area comprised of irrigated grass fields mixed with irrigated grasses such as smooth brome and red fescue, as well as wetland vegetation such as cattails, rushes, and foxtail barley.