

Inspection Photos

API: 043-06170

Operator: JAVERNICK OIL

Inspection Date: 10/15/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 043-06170 | Date: 10/15/2021

Inspection Photos



Photo 1. There is erosion along the access road that needs to be repaired and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06170 | Date: 10/15/2021

Inspection Photos



Photo 2. Facing southwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06170 | Date: 10/15/2021

Inspection Photos



Photo 3. Facing toward the pumpjack. The gate around the equipment needs to be kept closed. Weeds around the equipment need to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06170 | Date: 10/15/2021