

Inspection Photos

Location Name: KEHN USX AA-66N63W /1NWNE

Location #: 310872




Photo #1

Kehn USX AA 01-02 (05-123-27164) Wellsite

Plugged & Abandoned | PA

~ 10 yds.

prior insp.



Photo #2

Kehn USX AA 01-02 Wellsite

Plugged & Abandoned | PA

Corrective Action: Unnecessary Equipment

Well tubing

prior insp.

Inspection Photos

Location Name: KEHN USX AA-66N63W /1NWNE

Location #: 310872



Colorado Oil & Gas Conservation Commission
Weld County
+40.521058,-104.382027
29° NE
2021-10-18 15:23

Photo #3

Kehn USX AA 01-02 Wellsite

Plugged & Abandoned | PA

Unnecessary Equipment: Well tubing

Now removed



Colorado Oil & Gas Conservation Commission
Weld County
+40.519719,-104.379070
261° W
08-Jul-2021 16:51

Photo #4

Kehn USX AA 01-08 Battery site

Inactive | Shut-down

Equipment documented Loc. ID 302162

Formerly served:

Kehn USX AA 01-02

Plugged & Abandoned | PA

prior insp.

Inspection Photos

Location Name: KEHN USX AA-66N63W /1NWN

Location #: 310872



Photo #5

Kehn USX AA 01-08 Battery site

Inactive | Shut-down

Battery sign

prior insp.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources