

Inspection Photos
Location Name: Behring 23-7
Location ID: 332096



Photo 1 – Pit Area



Photo 2 Heater Treater

Inspection Photos
Location Name: Behring 23-7
Location ID: 332096



Photo 3 – Unmarked Riser




Photo 4 – Unmarked Risers



Inspection Photos
Location Name: Behring 23-7
Location ID: 332096



Photo 5 – Unmarked Riser