

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W /1NWSW

Location ID: 323935



Photo #5170 from entrance to location.



Photo #5171 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W /1NWSW

Location ID: 323935



Photo #5172 Location lacks stabilization.



Photo #5173 Insufficient tracking BMP at entrance to location.