

Inspection Photos  
Operator: Hilcorp  
API: 067-07403  
Date: 11/3/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the northern project area from the northwestern edge facing eastward. Dense kochia is present. Some desirable vegetation such as sand dropseed is also present. Edge of project area is line with green vegetation to weeds.



Photo 3. View of the western project area from the northwestern corner facing southward. Revegetation is comprised of alfalfa and smooth brome. Tall kochia, up to 4ft tall present.

Musk thistles



Photo 4/5. View of musk thistle rosettes, approximately 15 individuals observed.



Photo 6. View of reference area comprised of irrigated grass field. Grasses are not in identifiable condition at this time.