

Inspection Photos

Location Name: Francis D. Clark Unit B 1

Location ID: 317773

Dec 7, 2021 at 12:43:30 PM
40.046936,-104.863752
100 County Road 21
Fort Lupton CO 80621
United States
COGCC



Pic 1 wellhead

Dec 7, 2021 at 12:43:12 PM
40.047251,-104.863698
100 County Road 21
Fort Lupton CO 80621
United States
COGCC



Pic 2 ECD



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Francis D. Clark Unit B 1

Location ID: 317773

Dec 7, 2021 at 12:44:06 PM
40.047221,-104.863757
100 County Road 21
Fort Lupton CO 80621
United States
COGCC



Pic 3 tanks, labels are on opposite of oil tank.

Dec 7, 2021 at 12:44:50 PM
40.047391,-104.863877
100 County Road 21
Fort Lupton CO 80621
United States
COGCC



Pic 4 Separator, gas meter run, Pig Station, Automation communication equipment.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources