

Inspection Photos
Location Name: Shable LF 07-68HN
Location ID: 430730



Photo 1 – Weeds in Interim Reclamation Area



Photo 2 – Weeds in Interim Reclamation Area

Inspection Photos
Location Name: Shable LF 07-68HN
Location ID: 430730



Photo 3 – Wellhead



Photo 4 – Wellhead

Inspection Photos
Location Name: Shable LF 07-68HN
Location ID: 430730



Photo 5 – Wellhead



Photo 6 – Weeds in Interim Reclamation Area

Inspection Photos
Location Name: Shable LF 07-68HN
Location ID: 430730



Photo 7 – Weeds in Interim Reclamation Area



Photo 8 – Compressors



Inspection Photos
Location Name: Shable LF 07-68HN
Location ID: 430730



Photo 9 – Separators



Photo 10 – ECDs



Inspection Photos
Location Name: Shable LF 07-68HN
Location ID: 430730



Colorado Oil and Gas Conservation Commission
40.68433, -104.12196, 4853.2ft, 140°
12/28/2021 13:21:09



Colorado Oil and Gas Conservation Commission
40.68434, -104.12196, 4850.4ft, 159°
12/28/2021 13:21:15

Photo 11 – Tank Battery Sign

Photo 12 – Tanks Battery



Inspection Photos
Location Name: Shable LF 07-68HN
Location ID: 430730



Photo 13 – Weeds

Inspection Photos

Location Name: Stampede Federal 8-60-4 PAD

Location ID: 455627



Photo 15 – Sign at Entrance