



APR 07 1994

# WELL SITE INSPECTION FORM

Well Name GILLETTE #10 API Number 05-123-5676  
Operator McDORMICK O&G Permit # \_\_\_\_\_  
Location SWSE 7-9N-61W County WELD  
Field \_\_\_\_\_ Inspector R. VanSickle

AL/PA/DA Inspection Results: Well Status:  
Pass(Y) \_\_\_\_\_ Fail(N) \_\_\_\_\_ Date \_\_\_\_\_ ND \_\_\_\_\_ DG \_\_\_\_\_ WO \_\_\_\_\_ PR \_\_\_\_\_ SI ☒ TA \_\_\_\_\_

Date of Inspection Before/During Drilling \_\_\_\_\_

Surf. Csg. Size \_\_\_\_\_ Setting Depth \_\_\_\_\_ Cmt. Vol. \_\_\_\_\_ WOC time \_\_\_\_\_  
Consistent with APD casing Program? YES \_\_\_\_\_ NO \_\_\_\_\_ Returns \_\_\_\_\_  
Rig \_\_\_\_\_ BOP'S \_\_\_\_\_ Stage Tool Depth \_\_\_\_\_ Cmt. Vol. \_\_\_\_\_

Date of Inspection Before/During/After Completion \_\_\_\_\_

Prod. Csg. Set? \_\_\_\_\_ Completion Rig/Activity \_\_\_\_\_  
Drilling Pits: Closed \_\_\_\_\_ Open \_\_\_\_\_ Wellhead Installed: \_\_\_\_\_ Sign: Yes \_\_\_\_\_ No \_\_\_\_\_  
Tank ID: Yes \_\_\_\_\_ No \_\_\_\_\_ N/A \_\_\_\_\_ Skim Tank/Pit: \_\_\_\_\_ Prod. Tanks: ( ) \_\_\_\_\_ BBLs  
Equipment \_\_\_\_\_ Meter Run: Yes \_\_\_\_\_ No \_\_\_\_\_  
Bradenhead Press: \_\_\_\_\_ Fluid: No \_\_\_\_\_ Yes \_\_\_\_\_ Type \_\_\_\_\_ Well Cat. \_\_\_\_\_

## AL/PA/DA Inspection

Date Plugged: \_\_\_\_\_ Date Permit Expired: \_\_\_\_\_  
Hole Plugged: Yes \_\_\_\_\_ No \_\_\_\_\_ Pits Backfilled: Yes \_\_\_\_\_ No \_\_\_\_\_  
Material Buried: Yes \_\_\_\_\_ No \_\_\_\_\_ N/A \_\_\_\_\_ Site Clean: Yes \_\_\_\_\_ No \_\_\_\_\_  
Bond Release OK: Yes \_\_\_\_\_ No \_\_\_\_\_ Fed \_\_\_\_\_ Hole Marker: Yes \_\_\_\_\_ No \_\_\_\_\_

Date of Safety/Status Inspection 3-21-94

Comments: DIL SPILL INSIDE INADEQUATE BERMS. 2-300'S W/RETURNE  
IN WEST TANK. DIL @ WELL HEAD. FLOW LINE ON GROUND.

4-18-94 - Visited site w/operator - spill cleaned up, berms  
built up, new signs installed.

Violations: Yes ☒ No \_\_\_\_\_ Notice Sent: Yes \_\_\_\_\_ No ☒ Date Sent: \_\_\_\_\_