

Inventory to Dave Shoffm  
**COLORADO OIL & GAS CONSERVATION COMMISSION****NORTHEAST REGION INSPECTION REPORT**

00872905

☒ NOTICE OF UNSATISFACTORY INSPECTION

337 CAMBRIDGE STREET

☐ NOTICE OF SATISFACTORY INSPECTION

BRUSH, CO 80723 (970)-842-4465

API No. 05- 123 - 5676

LEASE NAME: Gillette 10

LOCATION: SWSE 9-9N-61W

OPERATOR: McCormick

DATE: 7-9-99 1730

INSPECTOR: ED BINKLEY MOBIL (970)-380-2683

INSP TYPE

10

INSP STATUS

TA

PA

Y

N

PASS/FAIL

P

F

VIOLATION

Y

N

NOV

Y

N

UIC VIOL TYPE

UA

☐

MI

☐

OP

☐

PA

☐

OT

☐

TBG/PKR LK

☐

CSG LK

☐ALL UIC VIOLATIONS REQUIRE  
NOAYS

Well ID Signs

(Rule 210)

- sign @ county road  
- not at well

Fences

(Rule 604.C.(3), 1003.A)

☐

Production Pits

(Rule 902, 903, 904)

EARTHEN PITS ONLY

PRODUCED WATER PITS

TOTAL #

2

OIL ACCUMULATION

☐

YES

☐

NO

☐

SKIMMING/SETTLING PITS

TOTAL #

1

COVERED

#

1

UNCOVERED

#

SPECIAL PURPOSE PITS

TOTAL #

LINED

#

UNLINED

#

COMMENTS/SIZE

100' x 200'

huge evap pits

SENSITIVE AREA

☐

YES

☐

NO

Tank Battery Equipment

(Rule 604)

1-300  
1-VHT☐

BURIED OR PARTIALLY BURIED VESSELS : #STEEL

#FIBERGLASS

#CONCRETE

#OTHER

Fire Walls/Berms/Dikes

(Rule 604)

☐

General Housekeeping

(Rule 603.G)

Shut in on 2 7/8 tubing -  
photo's -☐

Spills (Oil/Water)

(Rule 908)

☐

UIC ROUTINE INSPECTION

FILL OUT FORM 21

WHEN WITNESSING MIT

INJ PRESSURE

PSIG

T-C ANN PRESSURE

PSIG

BRHD PRESSURE

PSIG

COMMENTS

Drilling Well/Workover

(Rule 315)

JUL 19 1999

☐

Surface Rehabilitation

(Rule 317)

grassland -

☐

Miscellaneous

Quarrel hut w/ tools + cable rig

☐

CORRECTIVE ACTION REQUIRED:

post sign @ well head

Date Corrective Action Required By:

8-30-99

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.