

Inspection Photos
Operator: Simcoe
API: 067-06907
Date: 1/19/2022



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Revegetation is progressing with blue grama, western wheatgrass, and sand dropseed.



Photo 3. View of the southern project area from the southeastern corner facing westward.



Photo 4. View of dense Russian knapweeds within the southwestern project area. Approximately 500 observed.



Photo 5. View of reference area comprised of pinyon and juniper woodland with sagebrush, prickly pear, Indian ricegrass, and yucca in the understory.