

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

02/10/2022

Submitted Date:

02/11/2022

Document Number:

689501333

FIELD INSPECTION FORM
 Loc ID 327969 Inspector Name: Brown, Kari On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Evans, Jacob	303-328-5605	jacob.evans@chevron.com	Noble Environmental
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
481568	SPILL OR RELEASE	CL	02/07/2022		-	UPRC 27-9F Tank Battery	EI

General Comment:

This is an environmental inspection of Remediation Project 18876/Spill ID 481568 (CL). Any corrective actions from previous inspections that have not been addressed are still applicable.

There were no operator or contract environmental personnel on location at the time of this field inspection.

Photos attached to document site conditions.

Environmental**Spills/Releases:**

Type of Spill: _____

Estimated Spill Volume: _____

Comment: One AST remains on location. All other equipment has been removed. Spill excavation has been backfilled.Corrective Action: Submit an updated Supplemental Form 27 for the remediation of this release.

Date: 05/07/2022

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____

Long _____

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Spill/Remediation:Comment: No E&P Waste stored on location.Corrective
Action: _____

Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402954969	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5662991
689501334	Location Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5662988