WELL SITE INSPECTION FORM

C

WELL NAME #1 UEHLING 44-11 API NUMBER 05 - 061 - 06543

OPERATOR UPRC PERMIT NUMBER 89 881

LOCATION SESE 11 17S 42W COUNTY KIOWA

FIELD WILDCAT INSPECTOR SHELTON

AL/PA/(DA) INSPECTION RESULTS: WELL STATUS:

PASS(Y)___ FAIL(N) N DATE 11/8/89 FN___ FD___ WO___

==========

DATE OF INSPECTION BEFORE/DURING DRILLING___

CASING SIZE___ DEPTH SET___ CMT VOL___ WOC___

CONSISTENT WITH APD CASING PROGRAM?___ RETURNS___

RIG___ BOP'S___ CONTACT___

DATE OF INSPECTION BEFORE/DURING/AFTER COMPLETION___

PIPE SET?___ COMPLETION RIG/ACTIVITY___

DRILLING PITS: CLOSED___ OPEN___ WELLHEAD SYSTEM INSTALLED___

TANK ID: YES___ NO___ NA___ WELL SIGN: YES___ NO___

SKIM PIT: ___gal TANKS: ( )___bbls

EQUIPMENT___

BRADENHEAD PRESSURE ___ FLUID: NO___ YES___ TYPE___

METER RUN: YES___ NO___ WELL STATUS: PR___ TA___ SI___ WELL CAT 3-__

AL/PA/(DA) INSPECTION

DATE PLUGGED: VP 10/27/89 DATE PERMIT EXPIRED:___

HOLE PLUGGED: YES X NO___ PITS BACKFILLED: YES___ NO X

MATERIAL BURIED: YES___ NO___ NA X SITE CLEAN: YES X NO___

BOND RELEASE OK: YES___ NO X FED___ HOLE MARKER: YES___ NO X

DATE OF SAFETY/STATUS INSPECTION 11/8/89

COMMENTS NO SIGN OF SURF CSG / R-PIT OPEN, WET / PLOWED FIELD