

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

03/08/2022

Submitted Date:

03/08/2022

Document Number:

699105146

FIELD INSPECTION FORM
 Loc ID 459457 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
459461	WELL	DG	02/26/2022		123-48870	Gittlein D10-765	DG

General Comment:

LocationOverall Good: ☐**Signs/Marker:**

Type	DRILLING/RECOMP		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action: _____ Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 459461 Type: WELL API Number: 123-48870 Status: DG Insp. Status: DG**Well Drilling**

Rig: Rig Name: HP 517 Pusher/Rig Manager: Charles
 Permit Posted: SATISFACTORY Access Sign: SATISFACTORY

Well Control Equipment:

Pipe Ram: YES Blind Ram: YES Hydril Type: _____
 Pressure Test BOP: Pass Test Pressure PSI: 5000 Safety Plan: YES

Drill Fluids Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: YES Semi-Closed Loop: _____
 Multi-Well: YES Disposal Location: Waste Managment

Comment: [COGCC Inspection Report Summary](#)
 On Tuesday 3/8/22 at approximately 1040hrs I, Inspector Adam Burns,
 Conducted an on-site inspection at C34-14 Pad of Chevron
 Location ID: 459457 in Weld County, Colorado.
 While there, I observed Drilling Operations by H&P 517 on the Gittlein D10-765. Drilling
 at 15929' total depth. Drilling ahead.
 No violation of the COGCC rules were observed at the time of inspection.
 This is a summary of inspection report.

Corrective Action: _____ Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699105147	Inspection photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5684797