

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/08/2022

Submitted Date:

03/08/2022

Document Number:

698704050

FIELD INSPECTION FORMLoc ID 459457 Inspector Name: Serna, Abe On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Black, Nigel	(505) 333-1901	nlbl@chevron.com	All Inspections Durango

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
459461	WELL	XX	11/30/2018		123-48870	Gittlein D10-765	XX

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 459461 Type: WELL API Number: 123-48870 Status: XX Insp. Status: XX

Well Drilling

Rig: Rig Name: H&P 517 Pusher/Rig Manager: Charles
 Permit Posted: SATISFACTORY Access Sign: SATISFACTORY

Well Control Equipment:

Pipe Ram: YES Blind Ram: YES Hydril Type: _____
 Pressure Test BOP: Pass Test Pressure PSI: 5000 Safety Plan: YES

Drill Fluids**Management:**

Lined Pit: _____ Unlined Pit: _____ Closed Loop: _____ Semi-Closed Loop: YES
 Multi-Well: YES Disposal Location: Waste Management

Comment:

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
COGCC Inspection Report Summary On Tuesday 3/8/22 at approximately 1040hrs I, Inspector Abe Serna, Conducted an on-site inspection at C34-14 Pad of Chevron Location ID: 459457 in Weld County, Colorado. While there, I observed Drilling Operations by H&P 517 on the Gittlein D10-765. Drilling at 15929' total depth. Drilling ahead. No violation of the COGCC rules were observed at the time of inspection. This is a summary of inspection report.	sernaa	03/08/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698704051	Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5685348