

Inspection Photos

API: 071-06790

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 3/9/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06790 | Date: 3/9/2022

Inspection Photos



Photo 1. Facing southwest along the main road in Martinez Canyon. Last years flood caused stormwater to flow across the road due to culverts plugged up with debris.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06790 | Date: 3/9/2022

Inspection Photos



Photo 2. The culverts along the canyon crossing are filled in with debris which needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06790 | Date: 3/9/2022

Inspection Photos



Photo 3. Facing southeast toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06790 | Date: 3/9/2022