

**Inspection Photos**  
**Location Name: Piland 15-3**  
**Location ID: 320187**



**Photo #1 Tanks.**



**Photo # 2 separator.**





**Inspection Photos**  
**Location Name: Piland 15-3**  
**Location ID: 320187**



**Photo #3 Well Head.**



**Photo #4 No secondary containment for chemical barrel S/W of well head.**



**Inspection Photos**  
**Location Name: Piland 15-3**  
**Location ID: 320187**



**Photo #5 Unmaintained berms.**



**Photo #6 Unmaintained berms.**



**Inspection Photos**  
**Location Name: Piland 15-3**  
**Location ID: 320187**



**Photo #7 Unused equipment and debris.**



**Photo # 8 Unused equipment and debris.**



**Inspection Photos**  
**Location Name: Piland 15-3**  
**Location ID: 320187**



**Photo #9 Dead weeds/ debris.**



**Photo #10 Debris and no bull plug in P/R water tank.**



**Inspection Photos**  
**Location Name: Piland 15-3**  
**Location ID: 320187**



**Photo #11 No bull plug.**



**Photo #12 No bull plug.**