



Inspection Photos
Location Name: Yoxall Farms 4
Location ID: 318343



Pic 1 wellhead, pump jack, electric equipment



Pic 2 stained soil/mechanical issue with wellhead