

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/08/2022

Submitted Date:

04/21/2022

Document Number:

702700107**FIELD INSPECTION FORM**Loc ID 322954 Inspector Name: Anderson, Laurel On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Gorka, Ray		RGorka@kpk.com	KPK environmental
Graber, Nikki		nikki.graber@state.co.us	
Rickard, Jeff		JRickard@kpk.com	KPK environmental
MarCom	208-201-8280	PrimaryContractor@marcomllc.net	KPK Primary Contractor
KPK		cogcc@kpk.com	All Inspections
Binschus, Chris		chris.binschus@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
244529	WELL	PA	12/13/2019	GW	123-12324	FEDERAL WILDHORSE 15-31	PA

General Comment:**COGCC Environmental Inspection Report Summary:**

On April 8, 2022, at approximately 11:45 am a COGCC representative conducted an on-site inspection. While there, the COGCC representative monitored Final Reclamation progress for PA Well AP#123-12324 and its associated tank battery. Well was plugged and abandoned 05/24/2019.

Location: : **FEDERAL WILDHORSE-68N58W31SWSE**Operator: **KP Kauffman**Facility ID # **322954**County: **Weld**

During this inspection the following compliance issues were observed:

-Operator has failed to respond to the previous corrective action Field Inspection Report Doc.# 696301677 to remove unused electrical wires and remove deadman anchors (Comply with Rule 606.a.).

-Reclamation rules require reclamation activities to be conducted within twelve months of plugging on non-cropland. Well was plugged 05/24/2019. Operator has failed to complete final reclamation activities; gravel remains throughout the well and tank battery location and the well location access road, which has not been re-contoured or re-graded. Equipment remains at both the well and tank battery location (Comply with Rule 1004.).

-Weeds (Comply with Rule 606)

Refer to the attached inspection photos.

Note: Any corrective action(s) from previous inspections that have not been addressed are still applicable.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds throughout location.		
Corrective Action:	Comply with Rule 606.		Date: 04/25/2022
Type	STORAGE OF SUPL		
Comment:	Operator has failed to respond to the previous corrective action in Field Inspection Report Doc.# 696301677 to remove unused electrical wires and remove deadman anchors. Refer to the attached inspection photos.		
Corrective Action:	Comply with Rule 606.a.		Date: 11/04/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed **Fail** No disturbance /Location never built _____

Access Roads Regraded **Fail** Contoured **Fail** Culverts removed **Fail**

Gravel removed **Fail**

Location and associated production facilities reclaimed **Fail** Locations, facilities, roads, recontoured **Fail**

Compaction alleviation **Fail** Dust and erosion control _____

Non cropland: Revegetated 80% **Fail** Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: **This location does not comply with Rule 1004. Reclamation rules require reclamation activities to be conducted within twelve months of plugging on non-cropland. Well was plugged 05/24/2019. Operator has failed to complete final reclamation activities; gravel remains throughout the well and tank battery location and the well location access road, which has not been re-contoured or re-graded. Equipment remains at both the well and tank battery location.**

Corrective Action:	Comply with Rule 1004. Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards. Including stormwater and weed management. Corrective action date is being back dated to when all final reclamation activities should have been completed.	Date	05/24/2020
Overall Final Reclamation	Fail	Well Release on Active Location	<input type="checkbox"/>
		Multi-Well Location	<input type="checkbox"/>

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702700108	Inspection Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5730284